

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

EJ692 **1900 SHORE PARKWAY/BKLYN**
NW **1900 SHORE PARKWAY**
1/2-1 **NEW YORK CITY, NY**
0.997 mi.
5262 ft. **Site 3 of 3 in cluster EJ**

NY Spills **S102141122**
 N/A

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name: 1900 SHORE PARKWAY/BKLYN
Address: 1900 SHORE PARKWAY
City,State,Zip: NEW YORK CITY, NY
Spill Number/Closed Date: 9102439 / 1991-05-31
Facility ID: 9102439
Facility Type: ER
DER Facility ID: 281898
Site ID: 266222
DEC Region: 2
Spill Cause: Human Error
Spill Class: Not reported
SWIS: 2401
Spill Date: 1991-05-25
Investigator: SIGONA
Referred To: Not reported
Reported to Dept: 1991-05-31
CID: Not reported
Water Affected: GRAVESEND BAY
Spill Source: Vessel
Spill Notifier: Federal Government
Cleanup Ceased: 1991-05-31
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1991-06-03
Spill Record Last Update: 1991-06-11
Spiller Name: Not reported
Spiller Company: GAGLIANO'S MARINA
Spiller Address: Not reported
Spiller Company: 001
Contact Name: Not reported
DEC Memo: ""
Remarks: "CITIZEN'S BOAT IS BEING STAINED,POSSIBLE SUNK BARGE 1 WEEK AGO, DEC INVESTIGATED."

All Materials:

Site ID: 266222
Operable Unit ID: 956308
Operable Unit: 01
Material ID: 424954
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: 500.00
Units: G
Recovered: .00
Oxygenate: Not reported